


Painting The Stern Cabin Bilge



Ruder Gland Spanner

Rudder Gland

Emergency Steering Arm And
Fitting Position



Peter Looking For the Problem With The Prop



Peter Sorting Out The Problem With The Prop



The Problem Solved Thanks Peter



What Job Is Starting For The Aqua Now



New doors for the Aqua